


ORDER 20170223

\*\*\*\*\*

UNPLANNED MAINT. <InternalOrderSettlem.>



BUS2007-000020170223-PRD

Order	20170223	Ord.type	PM06
Sup. Order		Act.type	P03
Planning grp	H80	M.Plan	
Priority	1	Item	Main WC STABO001
STATUS	REL PCNF ESTC NMAT PRC SETC		
Description	BORDOVSKY STAB. LDAR PV-14502		

DUE DATE 04/21/2014

Func. Loc.	HZ-T0-EGF-A069254	Location
	BORDOVSKY STABILIZER	Room
	OCC/TRRC Number	
	Field Name	
	Meter ID Number	
Equipment	12355139	Cost Center A069254
	SCRUBBER FUEL GAS	ABC ind.
	Begin Guarantee	
	Warranty End	

Sort Field  
 Manufacturer : MANCHESTER TANK  
 Manuf. Serial no: 1245613  
 Model no :  
 Technical ID no:  
 Size/Dimension : 10" OD X 20" S/S

### Operation list

Op	Sub	Description	Workcenter
0010		BORDOVSKY STAB. LDAR PV-14502	MECHAPSM

BORDOVSKY STAB. LDAR PV-14502

Attached you will find the Requests For Repair for the Bordovsky Facility Leak Inspection (04-21-2014). Please fax, call or email the completed forms with the repair actions, date and time as indicated on the bottom of the form to the "Irvine Office". Please note the repair time frame for each leak is 15 days. Upon the repair, Avanti will return to re-inspect the repaired leaks. If you have any questions or concerns, please feel free to contact me at (210) 438-2850.

Kind Regards,

Javier Ramirez  
 Avanti Environmental, Inc.  
 Field Technician  
 3/4" VALVE LOCATED ON THE SOUTH EAST SIDE OF THE FUEL GAS SKID (PV-14502). VALVE IS LEAKING FROM VALVE STEM.  
 (SEE GREEN TAG ON COMPONENT)

**END OF ORDER**